

* INVOICE *

PAGE 2


SERVICE ADVISOR: 841

HOME :

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	14	CHEVROLET SILVERADO			14053/14053		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
31JAN15 DD		13JAN2018	WAIT 03AUG16		0.00	CASH	03AUG16
R.O. OPENED	READY	OPTIONS: ENG:5.3_Liter					
07:48 03AUG16	12:15 03AUG16						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	13594989		16682CT	RETAINER			(N/C)
2	332364		8950BOPCKT	(S)RETAINER			(N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D:							0.00

upon inspection found that lateral movement in drivers seat can be felt. repair in PI1183A as not been done to seat. performed repair to drivers seat as described in PI1183A installed retained on pivot bar and greased bar. installed shim on height adjuster and retainers in to front seat cover latches. verified repair no movement felt in seat.



CHEVROLET

"By law, you may choose another licensed Smog Check Facility to perform any needed repairs or adjustments which the Smog Check test indicates are necessary."
 I assume full responsibility and guarantee payment within your terms in event of nonpayment by any other party or parties billed for any portion of this work on my behalf.
 SUBJECT TO TERMS AND CONDITIONS ON REVERSE SIDE OF CUSTOMER COPY.
 Parts Designated with an asterisk (*) Indicates Limited Lifetime Warranty Applies for Customer Pay Repairs. I acknowledge notice and oral approval of an increase of the estimated price.
 CUSTOMER ACKNOWLEDGES RECEIPT OF A COPY HEREOF:

 SIGNED

ALL PARTS
 INSTALLED
 ARE NEW
 UNLESS
 SPECIFIED
 OTHERWISE.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00