

Document ID: 4487816

Shanay - TX
5911325**#PIC6110B: Timeshift Audio Playback Choppy Distorted or Garbled - (Apr 5, 2016)****Subject: Timeshift Audio Playback Choppy Distorted or Garbled****Models: 2015 Buick LaCrosse, Regal****2015 Cadillac ATS, CTS, ELR, Escalade models, SRX, XTS****2014 Chevrolet Silverado 1500****2015 Chevrolet Silverado****2015 Chevrolet Colorado, Corvette, Impala, Suburban, Tahoe****2014 GMC Sierra 1500****2015 GMC Sierra****2015 GMC Canyon, Yukon models****This PI was superseded to update the Recommendations/Instructions. Please discard PIC6110A.****Condition/Concern**

Some customers may comment that intermittently Timeshift audio playback is choppy, distorted, skipping, or garbled.

Recommendation/Instructions

Please do not replace any parts or make any repairs.

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Additional SI Keywords

chop distort skip garble pause

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION

Powertrain - rear
5/1100
engine trans
One axle
8/80
100

866-790-3600
Ext: 591349

Live
messenger

© 2016 General Motors. All rights reserved.

<https://gsi.ext.gm.com/gsi/showDoc.do?docSyskey=4487816&from=ns>

5/13/2016