


#17-NA-302: Dust Buildup Around Filler Cap Area - (Sep 27, 2017)

Subject: Dust Buildup Around Filler Cap Area



Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2018				
GMC	Sierra						

Involved Region or Country	North America and NA Export vehicles
Condition	Some customers may comment on excess amount dirt that can build up around the filler neck.
Cause	This condition may be caused when trucks are operated in high amount of dirt or dust which can migrate to the filler cap area.
Correction	<div></div> <p>Notify the customer that GM had made available a locking gas cap for drivers that operate in these dirty or dusty environments. This will protect the fill area from dirt intrusion and protect the fuel system.</p>

Parts Information

Causal Part	Description	Part Number	Qty
x	CAP ASM-F/TNK FIL LKG	84009129 (2017)	1
		84308352 (2018)	

Version	1
Modified	Released September 21,2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION