

To: William Sigmon Jr

228 43rd Avenue Dr NW

Hickory

28601

NC

Make: GMC Odo. In: 54,416
 Model: Sierra 1500 4WD Crew Cab 5 Odo. Out: 54,417
 Color: WHITE FROST TRICO, Next Service:
 VIN #: 3GTU2NEJ0HG136971 In Service Date: 01/30/2017
 Date In: 07/14/2020 11:31 Cases: 2
 Date Out: 07/14/2020 11:31
 Ext. War - - (mo/) - D: \$0.00
 Promised Time: 07/14/2020 05:00:00 PM Call When Ready;

Case: 1 think torque converter is going out - going up hill sounds like going over rumble strips -perform SP

Quantity	Description/Correction	Retail	Price	Total
20.00	19417904 - Fluid- LV ATF HP - Warranty (FP)	\$8.45	\$0.00	\$0.00

- Tech Cause: recall
- Tech Comments: performed shutter flush - Warranty
- Completed By: Burris, Stephen D.

Misc \$0.00 Labor \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

Case: 3 MULTI-POINT VEHICLE INS (MULTI-POINT VEHICLE INSPECTION)
 CAUSE: MULTI-POINT VEHICLE INSPECTION
 CORRECTION: Perform MULTI-POINT VEHICLE INSPECTION

Quantity Description/Correction

Price	Total
\$0.00	\$0.00

- MULTI-POINT VEHICLE INS (MULTI-POINT VEHICLE INSPECTION) - CAUSE: MULTI-POINT VEHICLE INSPECTION - CORRECTION: Perform MULTI-POINT VEHICLE INSPECTION - Internal
- Completed By: Burris, Stephen D.

Misc \$0.00 Labor \$0.00 Parts \$0.00 Prepaid Parts Amt: \$0.00 Case Total: \$0.00

\$0.00