

Caused by

Diagnostic circuit check and found history code P0300 stored. Monitored misfire data and noted a misfire on #4 cylinder. Removed the valve cover and found the #4 cylinder exhaust valve spring broken. Removed the cylinder head and valve. Inspected the valve and piston. No damage beyond the broken valve spring was found.

Tech: 7456	(456)			Warranty
Installed 12688943	:SL-N-GASKET (00289-CT)		Qty: 1	Warranty
Installed 12619787	:SL-N-GASKET (00423-CKT)		Qty: 1	Warranty
Installed 12657093	:SL-N-GASKET (03270-CKT)		Qty: 1	Warranty
Installed 12346290	:N-COOLANT (08800-BOPCKT)		Qty: 1	Warranty
Installed 12691120	:SL-N-SPRING (00303-CKT)		Qty: 2	Warranty
Installed 11546959	:SL-N-BOLT (00293-CKT)		Qty: 10	Warranty
Installed 12677002	:SL-N-PIPE (03163-CT)		Qty: 1	Warranty
Installed 12679463	:SL-N-PIPE (03163-CT)	12679	Qty: 1	Warranty
Installed 12345	:PRICE DIFFERENCE		Qty: 1	Warranty
Installed 12690385	:SL-N-FILTER (01836-BOPCKT)		Qty: 1	Warranty