

#PIP5228D - Vibration During Active Fuel Management V4 Mode Operation 1200 à 1400 Engine RPM - (Mar 16, 2017)

Subject:
Vibration During Active Fuel Management V4 Mode Operation 1200 – 1400 Engine RPM

...

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|-----------|-------------|----|------|-----|----------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado | 2014-2017 | | All | All | 4.3L LV3 | All |
| GMC | Sierra | 2014-2017 | | All | All | 4.3L LV3 | |