



2017 GM Vehicle Diagnostic Report

Vehicle Information

2017 / GM / GMC /
VIN: 1GKS17EC5HR103833

Odometer Reading: 311482km
License Plate: 1940



Scan to download
PDF

Customer Information

Name: --

Device information

Scanner: MaxiCheck MX900
Version: V11.00

Serial Number: DR8GR6C01289
Repair Order Number: DR8GR6C0128920240808174813409

System Scanned (18)

System	Status/DTC
Engine control module	 0
Transmission control module	 0
Electronic brake control module	 1
Inflatable restraint sensing and diagnostic module	 0
Instrument cluster	 0
Power steering control module	 3
Steering wheel angle sensor module	 0
Parking assist control module	 1
Amplifier	 1
Body control module	 0
Frontview camera module	 0
Human machine interface control module	 0
HVAC control module	 1
HVAC controls	 1
Passenger presence module	 0
Radio	 1
Radio controls	 1

Seat memory control module - driver

✔

0

 DTC (10)

Electronic brake control module (1 DTC)

DTC	Description	Status
C0710:4B	Steering position signal calibration not learned	DTC history status : History DTC current status : Current This ignition cycle : Failed MIL status : Requested

Power steering control module (3 DTCs)

DTC	Description	Status
C0544:5A	Steering wheel angle sensor data not plausible	DTC history status : History Since DTC clear : Passed Last test : Failed current DTC This ignition cycle : Passed MIL status : Requested
U0415:71	Invalid data received from electronic brake control module invalid data	DTC history status : History Since DTC clear : Passed Last test : Failed current DTC This ignition cycle : Passed MIL status : Not requested
U0428:71	Invalid data received from steering wheel angle sensor module invalid data	DTC history status : History Since DTC clear : Passed Last test : Failed current DTC This ignition cycle : Passed MIL status : Requested

Parking assist control module (1 DTC)

DTC	Description	Status
B1405:02	Control module voltage reference output 2 circuit short to ground	DTC history status : History DTC current status : Current

Amplifier (1 DTC)

DTC	Description	Status
B101D:31	Electronic control unit hardware internal checksum error	DTC history status : History DTC current status : Current

HVAC control module (1 DTC)

DTC	Description	Status
B3782:05	Air flow control rear feedback circuit high voltage/open	DTC history status : History DTC current status : Current

HVAC controls (1 DTC)

DTC	Description	Status
B1325:03	Control module power circuit low voltage	DTC history status : History DTC current status : Not current

Radio (1 DTC)

DTC	Description	Status
B1325:03	Control module power circuit low voltage	DTC history status : History DTC current status : Not current

Radio controls (1 DTC)

DTC	Description	Status
B1325:03	Control module power circuit low voltage	DTC history status : History DTC current status : Not current

Technician Notes

Customer Name:

Technician:

Date:

Note: Please save a copy of this report for your records.