

# GMC\_Sierra DTC Report

## Diagnostic

Company: **Fowlers**  
 Telephone: 7097277262  
 Address: 1005 Bauline line ext

Mailbox: --  
 Website: --

### ► Basic Information

VIN: 1GTP9EED0KZ160844      Mileage: 148290km  
 Plate No.: --      Report Date: 2025-08-27 04:52:46  
 SN: VD70-WE46B2F      Version: V5.7.32\_11.45  
 Path: GM->V14.90->Automatic Detection->2019->GMC->Sierra

### ► System Scan Result

26 systems detected: 7 systems related to fault codes, 14 fault codes

NO.	System Name		Status
1	Engine Control Module(ECM)		▲ 6
2	Brake System Control Module(BSCM)		▲ 2
3	Video Processing Control Module(VPCM)	ADAS <sup>®</sup>	▲ 2
4	Body Control Module(BCM)	(!)	▲ 1
5	Parking Assist Control Module(PACM)		▲ 1
6	Amplifier(AMP)		▲ 1
7	Transfer Case Control Module(TCCM)	ADAS <sup>®</sup>	▲ 1
8	Transmission Control Module(TCM)		✓
9	Inflatable Restraint Sensing and Diagnostic Module(IRSDM)		✓
10	Instrument Cluster(IC)		✓
11	HVAC Control Module(HVACCM)		✓
12	HVAC Controls(HAVCC)		✓
13	Telematics Communication Interface Control Module(TCICM)		✓
14	Power Steering Control Module(PSCM)		✓
15	Seat Memory Control Module - Driver(SMCM_D)		✓
16	Passenger Presence Module(PPM)		✓

17	Frontview Camera - Windshield(FCM)	ADAS <sup>3</sup>	✓
18	Radio(RADIO)		✓
19	Keyless Entry Control Module(KECM)		✓
20	Trailer Lighting Control Module(TLCM)		✓
21	Left Side Object Detection Control Module(LSODCM)		✓
22	Right Side Object Detection Control Module(RSODCM)		✓
23	Trailer Tire Pressure Indicator Module(TTPIM)		✓
24	Steering Column Lock Control Module(SCLCM)		✓
25	Serial Data Gateway Module - Processor 1(SDGM_P1)		✓
26	Serial Data Gateway Module - Processor 2(SDGM_P2)		✓

## ► Trouble Code

### ■ Engine Control Module(ECM) (DTC Amount: 6)

NO.	DTC Code	Trouble Code Descriptions	Status
1	U0101-00	Lost Communication with Transmission Control Module	Current
2	U0102-00	Lost Communication with Transfer Case Control Module	Current
3	U0129-00	Lost Communication with Brake System Control Module	Current
4	U0140-00	Lost Communication with Body Control Module	Current
5	U18A2-00	Lost Communication with Fuel Pump Driver Control Module	Current
6	U216A-00	Lost Communication with Front Object Detection Control Module	Current

### ■ Brake System Control Module(BSCM) (DTC Amount: 2)

NO.	DTC Code	Trouble Code Descriptions	Status
1	U0100-00	Lost Communication with Engine Control Module	History
2	U0403-72	Invalid Data Received From Transfer Case Control Module - Message Counter Incorrect	History

### ■ Body Control Module(BCM) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	B3109-00	Keyless Entry Transmitter 1 Battery	Current

### ■ Parking Assist Control Module(PACM) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	U0422-00	Invalid Data Received From Body Control Module	History

**Amplifier(AMP) (DTC Amount: 1)**

NO.	DTC Code	Trouble Code Descriptions	Status
1	U18B4-00	Lost Communication with Radio on Ethernet Bus	History

**Video Processing Control Module(VPCM) (DTC Amount: 2)**

NO.	DTC Code	Trouble Code Descriptions	Status
1	B395B-08	Sideview Camera - Left - Performance - Signal Invalid	Current
2	B399C-02	Sideview Camera - Left Supply Circuit - Short to Ground	Current

**Transfer Case Control Module(TCCM) (DTC Amount: 1)**

NO.	DTC Code	Trouble Code Descriptions	Status
1	P062F-00	Control Module Long Term Memory Performance	Current

\*This report is only responsible for the results of this detection